


Unit Mounted X-Ray Viewer (153700)

ACCESSORY PARTS LIST



DA117300i

Item	Part No.	Description	Qty	Item	Part No.	Description	Qty
	153700-00	110 V Midmark X-Ray Viewer Assy. (includes items 1 thru 18)	1	7	• 120964-50	• Tray Arm Spacer	1
	153700-01	220 V Midmark X-Ray Viewer Assy. (includes items 1 thru 13 & 15 thru 18)..	1	8	• 120965	• Dowel Pin (apply adhesive #K906111)	1
1	• 153152	• 110 V Viewer Assembly (includes items 2, 3 & 4).....	1	9	• 120982	• Screw	3
	• 153152-01	• 220 V Viewer Assembly (includes items 2, 3 & 4).....	1	10	• 118047	• Washer	1
2	••119905	••Screw	4	11	• 108850	• Screw	1
3	•• 121301-50	•• Mounting Post	2	12	• 153153	• Power Cable	1
4	•• 122631-50	•• Switch Mounting Cap.....	2	13	• 015-1609-00	• Power Cable	1
5	• 122076-50	• Bar Support	1	14	• 110994	• Plug (110 V models only).....	1
6	• 117558	• Screw	2	15	• 015-0013-02	• Cable Tie	1
				16	• 108850	• Set Screw	1
				17	• 030-1420-50	• X-Ray Viewer Tube Weldment	1
				18	• TPW1800	• Installation Instructions (not shown) ...	1
				19	122727	• Butt Splice Terminal (not shown).....	3

Always Specify Model & Serial Number